



Inspection Report

Inspection Date: 2023/07/21

Excavators

General Information

Maker	KUBOTA		
Model Number	U-17		
Year	2011		
Hour (h)	1313	Meter	Working
Serial Number	16132		

Options


- Multilever	- Speed changer
- Blade	- Breaker Pipings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		Oil leak	No	Big
Bucket		No	No	Big
Bucket Size (mm)	400			

Note for External Appearance

- The body is corroded and decayed
- The canopy is cracked



Undercarriage


Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Width adjustable shoe type
- Shoes are unable to adjust because the switching lever does not work
- The shoe track frame is corroded




Engine

Model	D902
Serial Number	BU0948
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak


Note for Operating Component

- The left travel lever is stiff and won't move properly



Note for Engine

- The battery is flat. The machine worked normally with the booster cables.



Admin No. 3000052406