



Inspection Report

Inspection Date: 2021/08/26

Excavators

General Information

Maker	HITACHI		
Model Number	ZX200-3		
Year	2010		
Hour (h)	8640	Meter	Working
Serial Number	HCM1U100C00215870		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	Oil leak	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	1025			

Note for External Appearance

- The body is repainted



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	700	700
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- One side of the arm has been reinforced



Note for Undercarriage



Engine

Model	AI-4HK1XYSA-02
Serial Number	4HK1-468105
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component

- A rear-view camera is installed



Note for Engine



Admin No. 3000034527