



Inspection Report


Inspection Date: 2018/03/18

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-40-3S		
Year	2005		
Hour (h)	4014	Meter	Working
Serial Number	30480		


Options	
- CAB	- Speed changer
- Multilever	
- Blade	- Pipings
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	Scratch	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		550		


Note for External Appearance



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage


Engine	
Model	V2203KA
Serial Number	V2203-5N1153
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Oil oozing

Note for Operating Component
- The seat is partly worn and torn
- Heater
- The cabin is partly rusty


Note for Engine
Exhaust leak from the muffler


Lot No ARA013-0039 Admin No. 2018030700