



Inspection Report

Inspection Date: 2018/05/12

Excavators

General Information

Maker	KOBELCO		
Model Number	SK225SR		
Year	2013		
Hour (h)	2787	Meter	Working
Serial Number	YB06-03944		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| | - Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
	Arm	No	No	No
	Bucket	No	Yes	Small
	Bucket Size (mm)	1020		

Note for External Appearance

Repainted



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure

2 sides of the arm are reinforced



Note for Undercarriage

- Spin turns are unchecked
- The shoe plates are partly damaged
- Oil oozing from the right reduction drive
- Oil oozing from some of the left lower rollers
- Some of the left lower rollers are broken



Engine

Model	J05E-TA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

Oil leak from the engine oil element



Admin No. 2018020320