



Inspection Report

Inspection Date: 2022/04/07

Excavators

General Information

Maker	KOBELCO		
Model Number	SK40SR-3		
Year	2008		
Hour (h)	6017	Meter	Working
Serial Number	PH06-05385		

Options


- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	No
Bucket		No	No	Small
Bucket Size (mm)	530			

Note for External Appearance

- Partially rusted and damaged
- Dents on the rear cover




Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


Note for Upper Structure

- Alarm at the crane mode (the load meter does not light up)
- Oil oozing from the front swing cylinder



Note for Undercarriage

- Almost half of pads are missing




Engine

Model	4TNV88-XYV
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The engine key is broken
- The interior is rusted
- The seat is torn



Note for Engine



Admin No. 3000039927