



Inspection Report

Inspection Date: 2026/06/04

Excavators

General Information

#ERROR!	YANMAR		
Model Number	VIO30-6		
Year	2014		
Hour (h)	2658	Meter	Working
Serial Number	63401		

Options

- | | |
|--------------|-----------------|
| - CAB | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		500		

Note for External Appearance

- Repainted
- The body has some rust and scratches



Undercarriage

Shoe Type	Rubber	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Oil oozing from some lower rollers



Engine

Model	3TNV88-ESBV
Serial Number	P5035
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component



Note for Engine



Admin No. 3000086130