



Inspection Report

Inspection Date: 2019/03/11

Generator

General Information

Maker	DENYO
Model Number	DCA-15SPK
Year	
Hour (h)	5536
Serial Number	2891196

Note for External Appearance

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Radiator	OK
Water Pump	No water leak
Injection Pump	Fuel oozing

Note for Control Panel

- Operational conditions are unchecked
- According to the seller, the engine works properly, but the generator has some problems

Note for Engine

- The battery is flat
- Operational conditions of the engine and the generator are unchecked
- Oil oozing from the water pump

Admin. No. 2019030013

*This report is only for your reference. We are not responsible for the actual condition of checked item.