



# Inspection Report

Inspection Date: 2019/02/14

## Roller

### General Information

Maker	SAKAI
Model Number	TG350
Year	不明
Hour (h)	1570
Serial Number	10483


### Engine

Model	3KR1HA-22
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	Not enough cooling water

### Note for External Appearance



### Note for Undercarriage



### Note for Operating Component

The seat is partly torn



### Note for Engine



Admin. No. 2019020075

\*This report is only for your reference. We are not responsible for the actual condition of checked item.