



Inspection Report


Inspection Date: 2018/05/17

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK40SR-3		
Year	2005		
Hour (h)	3814	Meter	Working
Serial Number	PH05-03585		


Options	
- CNP	
- Blade	- Breaker Pipings
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)		-		


Note for External Appearance


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Oil oozing from the swing cylinder


Note for Undercarriage
Some rubber pads are lost


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018050411