



Inspection Report

Inspection Date: 2026/07/27

Excavators

General Information

#ERROR!	KOMATSU		
Model Number	PC05-1A		
Year	2015		
Hour (h)	903	Meter	Working
Serial Number	17333		

Options

--	--

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		290		

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	150	150
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The travel motor cover is missing



Engine

Model	1D78E-1A
Serial Number	K00179
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 3000087889

*This report is only for your reference. We are not responsible for the actual condition of checked item.