



Inspection Report

Inspection Date: 2024/12/14

Excavators

General Information

Maker	KOMATSU		
Model Number	PC128US-8		
Year	2008		
Hour (h)	7588	Meter	Working
Serial Number	KMTPC189H01024346		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	840			

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Steel		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage



Engine

Model	SAA4D95LE-5-A
Serial Number	508323
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000067380