



Inspection Report


Inspection Date: 2018/03/17

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-305		
Year	2008		
Hour (h)	3969	Meter	Working
Serial Number	70844		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		430		


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The connecting parts of the bucket have been repaired


Note for Undercarriage


Engine	
Model	D1703
Serial Number	8S0774
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly worn and torn


Note for Engine


Lot No ARA013-0033 Admin No. 2018030706