



# Inspection Report

Inspection Date: 2022/08/18

## Excavators

### General Information

<b>Maker</b>	CAT		
<b>Model Number</b>	320D		
<b>Year</b>	2007		
<b>Hour (h)</b>	6715	<b>Meter</b>	Working
<b>Serial Number</b>	CAT0320DCBWZ00611		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	1020			

### Note for External Appearance

- The bottom of the bucket is damaged
- The body is rusty and decayed
- The cover is deformed
- The undercover is decayed



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	Oil oozing	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

- The bucket pin is missing



### Note for Undercarriage

- The shoes and the frame are deformed
- The undercarriage is rusty



### Engine

<b>Model</b>	C6.4
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Yes
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is torn



### Note for Engine

- Oil oozing from the whole engine



Admin No. 3000043116