



Inspection Report


Inspection Date: 2018/06/14

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO30-3		
Year	2005		
Hour (h)	4580	Meter	Working
Serial Number	31497B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pippings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		470		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	NG	OK
Sprocket	OK	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
- The left rubber shoe is partly cracked - The right rubber shoe has deteriorated over time


Engine	
Model	3TNV82A-XBV
Serial Number	23220
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018060993