



# Inspection Report


Inspection Date: 2018/10/25

## Excavators


General Information			
Maker	KUBOTA		
Model Number	K-008-2		
Year			
Hour (h)	1704	Meter	Working
Serial Number	20172		


Options	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Big
Bucket Size (mm)		300		


Note for External Appearance


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	180	180	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
The rubber shoes have deteriorated over time and are worn


Engine	
Model	D722
Serial Number	Y5730B
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	-

Note for Operating Component


Note for Engine


Admin No. 2018100234