



# Inspection Report


Inspection Date: 2018/08/06

## Excavators


General Information			
Maker	SUMITOMO		
Model Number	SH200HD-3		
Year			
Hour (h)	8924	Meter	Working
Serial Number	200A3-6951		


Options	
- CAB	- Speed changer
	- Air conditioner
	- Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	Oil leak	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		1030		


Note for External Appearance
Repainted


Undercarriage			
Shoe Type	Steel		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- High boss boom
- 2 sides of the arm have been reinforced


Note for Undercarriage


Engine	
Model	BB-6BG1 TRB
Serial Number	224147
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	-

Note for Operating Component


Note for Engine


Admin No. 2018080007