



Inspection Report

Inspection Date: 2018/09/24


Excavators

General Information			
Maker	YANMAR		
Model Number	ViO70-3A		
Year	2012		
Hour (h)	366	Meter	Working
Serial Number	37201		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Pipings
- Arm Crane	
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		645		

Note for External Appearance



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
2 sides of the arm have been reinforced




Note for Undercarriage



Engine	
Model	4TNV98-ZWBV
Serial Number	N2468
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018090446