



# Inspection Report

Inspection Date: 2019/10/04

## Excavators

### General Information

<b>Maker</b>	CAT		
<b>Model Number</b>	320D		
<b>Year</b>			
<b>Hour (h)</b>	12613	<b>Meter</b>	Working
<b>Serial Number</b>	CAT0320DVBWZ06501		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Arm Crane  |                   |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		Oil oozing	No	No
Bucket		No	No	Small
Bucket Size (mm)	1180			

### Note for External Appearance

The body is partly rusty and damaged



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	Oil oozing	
	Left	Right
Shoe Width (mm)	800	800
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

The tip of the arm has some dents



### Note for Undercarriage



### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	Oil shortage
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Yes
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 2019090645