



Inspection Report

Inspection Date: 2023/12/01

Roller

General Information

| | |
|----------------------|--------------|
| Maker | KOMATSU |
| Model Number | JV40CW-5E0 |
| Year | 2005 |
| Hour (h) | 2694 |
| Serial Number | JV40CW5-6361 |

Engine


| | |
|-------------------------|---------------|
| Model | 3D84E-5NCB |
| Serial Number | 05412 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Water Pump | No water leak |
| Radiator | OK |

Note for External Appearance

- The side and front mirror are missing



Note for Undercarriage



Note for Operating Component



Note for Engine



Admin. No. 3000053529

*This report is only for your reference. We are not responsible for the actual condition of checked item.