



Inspection Report

Inspection Date: 2019/02/23

Roller

General Information

Maker	HITACHI
Model Number	CC135C
Year	
Hour (h)	3466
Serial Number	8U1P010157


Engine

Model	3LD2
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK


Note for External Appearance




Note for Undercarriage



Note for Operating Component



Note for Engine



Admin. No. 2019020726

*This report is only for your reference. We are not responsible for the actual condition of checked item.