



Inspection Report

Inspection Date: 2021/08/10

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA150-1
Year	1992
Hour (h)	7628
Serial Number	W006-30750

Note for External Appearance

- The body is rusty and decayed



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure

- The bucket is partly deformed



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- The roof is damaged
- Oil leak from the brake pedals
- Mileage: 39,932km
- There are 2 seats



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- 4 tires are new



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000033958

*This report is only for your reference. We are not responsible for the actual condition of checked item.