



Inspection Report


Inspection Date: 2022/08/31

Excavators


| General Information | | | |
|---------------------|-------------------|-------|---------|
| Maker | HITACHI | | |
| Model Number | ZX75US-3 | | |
| Year | 2014 | | |
| Hour (h) | 3444 | Meter | Working |
| Serial Number | HCM1P300V00066395 | | |


| Options | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| | - Breaker Pplings |
| - EPA | |

| Upper Structure | | | | |
|------------------|-------|------------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | Oil oozing | No | Small |
| Bucket Size (mm) | | 645 | | |


| Note for External Appearance |
|---|
| - The cover has some dents |
|  |

| Undercarriage | | | |
|-----------------|-------------|-------|--|
| Shoe Type | Steel | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 600 | 600 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

| Note for Upper Structure |
|---|
| - The bucket side cutters are missing |
| - The arm has been reinforced |
|  |

| Note for Undercarriage |
|---|
|  |

| Engine | |
|------------------|---------------|
| Model | AU-4LE2XYS-01 |
| Serial Number | 4LE2-623220 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
|  |

| Note for Engine |
|---|
|  |

Admin No. 3000042434