

SR-G2000 Crusher/Recycler/Screen

BASIC INFORMATION

Inspection Date		Model	SR-G2000	Serial No.	147
Date of Manufacture		Hourmeter	8389 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.		Job Status	Rental
Accident History		Type of Shoe	Grouser	Stamp	
Others					

OPERATION

Engine	Normal	Exhaust Gas Color	Normal 経年相応	Traveling	Normal
Clutch		Crusher/Screen		Conveyor Device	Normal
Feeder	Normal	Console	Not Working Properly 配線劣化 不調時アリ	Remote Control	Malfunction クレーン有線リモコン作動不良

UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Moderate/Within Service Limit	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread (Right)	Moderate/Within Service Limit	Wear: Track Link Tread (Left)	Moderate/Within Service Limit	Wear: Track Link Pins (Right)	Moderate/Within Service Limit
Wear: Track Link Pins (Left)	Moderate/Within Service Limit	Wear: Track Shoe/Rubber Shoe	Moderate/Within Service Limit	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Wear: Upper Rollers	Moderate/Within Service Limit	Wear: Lower Rollers	Moderate/Within Service Limit	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler (Right)	Moderate/Within Service Limit	Wear: Front Idler (Left)	Moderate/Within Service Limit
Wear: Sprocket (Right)	Moderate/Within Service Limit	Wear: Sprocket (Left)	Moderate/Within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

FRONT & PINS

Wear/Deformation: Tooth/Cutters		Wear/Deformation: Screen		Wear/Deformation: Jaw Crusher	
Crusher V belt		Wear/Deformation: Conveyor	Wear: Moderate/Within Service Limit	Wear: King Pins	

OIL/WATER/AIR LEAK

Aux. Cylinder (Right)		Aux. Cylinder (Left)	No	Oil Leak: Engine	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	No	Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Center Joint		Oil Leak: Crusher Device		Oil Leak: Conveyor Motor	Slight Film
Oil Leak: Crushing Motor		Oil Leak: Pump Device	Slight Film		

APPEARANCE

Main frame	Good Condition	Track Frame	Good Condition	Hopper	Good Condition
Side Covers	Rusted/Corroded				

INTERIOR

Console					
---------	--	--	--	--	--

OVERALL RATING

Appearance Evaluation	Repainted	Rust/Corrosion	Moderate	Overall Rating	Fair
Special Notes	電装系劣化アリ				