



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	AICHI
Model Number	SR21A
Year	2005
Hour (h)	8280
Serial Number	688494

Note for External Appearance

- Repainted
- The basket has dents (see photo)
- Some covers are detached

Engine

Model	
Serial Number	
Engine Oil Leak	#N/A
Engine Oil Gauge	#N/A
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	#N/A
Water Pump	#N/A
Injection Pump	#N/A

Note for Control Panel

- Some parts of the control lever are detached

Note for Engine

Other Information

- It is unable to go to the right and left when traveling
- It is able to go forward and backward
- The shoes have kinks

Admin. No. 3000060727

*This report is only for your reference. We are not responsible for the actual condition of checked item.