



Inspection Report

Inspection Date:

Vehicle

General Information

Maker	ISUZU
Model Number	TKG-NKR85N
Year	2013
Hour (h)	3660
Serial Number	NKR85-7032183

Note for External Appearance

- Partly rusty and damaged
- AICHI SB12A #743469
- Maximum Aerial Platform: 12.0m

Engine

Model	4JJ1
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

- Mileage: 51,307 km
- AT

Note for Engine

Other Information

Admin. No. 3000047176

*This report is only for your reference. We are not responsible for the actual condition of checked item.