



# Inspection Report

Inspection Date:

## Aerial Work Platform

### General Information

<b>Maker</b>	AICHI
<b>Model Number</b>	SV04B
<b>Year</b>	2005
<b>Hour (h)</b>	
<b>Serial Number</b>	688920

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	#N/A
<b>Engine Oil Gauge</b>	#N/A
<b>Exhaust Color</b>	#N/A
<b>Blow-by</b>	#N/A
<b>Engine Sound</b>	#N/A
<b>Radiator</b>	#N/A
<b>Water Pump</b>	#N/A
<b>Injection Pump</b>	#N/A

### Note for External Appearance

- The pedal is detached

### Note for Control Panel

### Note for Engine

- Battery type

### Other Information

- The battery is not charged  
- Operation is unchecked  
- Working hour is unknown

Admin. No. 3000045989

\*This report is only for your reference. We are not responsible for the actual condition of checked item.