



Inspection Report

Inspection Date: 2023/02/14

Excavators

General Information

Maker	KOBELCO		
Model Number	SK80UR-6		
Year	2013		
Hour (h)	5126	Meter	Working
Serial Number	YR10-10148		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	670			

Note for External Appearance

- Partly repainted




Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- The bucket has some dents



Note for Undercarriage

- The rubber pads are deteriorated and partly cracked



Engine

Model	4LE2XCUAB
Serial Number	4LE2-606025
Engine Oil Leak	Oil oozing
Engine Oil Gauge	Oil shortage
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000045638