



# Inspection Report


Inspection Date: 2018/06/15

## Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-303S		
Year	2006		
Hour (h)	5298	Meter	Working
Serial Number	60949		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		430		


Note for External Appearance
The caution plate is partly damaged



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Note for Upper Structure
- The inside of the arm has some dents
- Upper structure movement is unchecked


Note for Undercarriage
- Oil oozing from one of the right lower rollers
- Traveling motion is unchecked


Engine	
Model	D1503-KA
Serial Number	06L1098
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Oil oozing

Note for Operating Component
The seat has been fixed


Note for Engine
Engine movement is unchecked because the battery is flat


Admin No. 2018060878