



Inspection Report

Inspection Date: 2019/02/22


Excavators

General Information			
Maker	KUBOTA		
Model Number	RX-305		
Year	2008		
Hour (h)	5442	Meter	Working
Serial Number	70617		

Options	
- CNP	- Speed changer
- Blade	- Pipings
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	Yes	Big
Bucket Size (mm)	420			

Note for External Appearance




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The bucket is worn




Note for Undercarriage
- The rubber shoes have deteriorated over time and are partly worn
- Oil oozing from around the swivel



Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2019020504