



# Inspection Report

Inspection Date: 2018/12/12

## Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	SW350-1
<b>Year</b>	2004
<b>Hour (h)</b>	1952
<b>Serial Number</b>	10535

### Engine

<b>Model</b>	3LD1 PA-29
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for External Appearance



### Note for Undercarriage



### Note for Operating Component



### Note for Engine



Admin. No. 2018120051

\*This report is only for your reference. We are not responsible for the actual condition of checked item.