



# Inspection Report


Inspection Date: 2018/06/15

## Excavators


| General Information |         |       |         |
|---------------------|---------|-------|---------|
| Maker               | YANMAR  |       |         |
| Model Number        | Vio20-3 |       |         |
| Year                | 2006    |       |         |
| Hour (h)            | 2876    | Meter | Working |
| Serial Number       | 33266B  |       |         |


| Options      |                 |
|--------------|-----------------|
| - CNP        | - Speed changer |
| - Multilever |                 |
| - Blade      |                 |

| Upper Structure  |       |          |              |       |
|------------------|-------|----------|--------------|-------|
|                  |       | Cylinder |              | Play  |
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | No    |
|                  | Right | N/A      | N/A          |       |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Big   |
| Bucket Size (mm) |       | 420      |              |       |


| Note for External Appearance  |
|---|
| The roof of the canopy is partly cracked  |
|  |

| Undercarriage   |             |       |  |
|-----------------|-------------|-------|--|
| Shoe Type       | Rubber      |       |  |
| Swing Circle    | No oil leak |       |  |
|                 | Left        | Right |  |
| Shoe Width (mm) | 250         | 250   |  |
| Idler           | OK          | OK    |  |
| Sprocket        | OK          | OK    |  |
| Pin Bush        | OK          | OK    |  |
| Upper Roller    | OK          | OK    |  |
| Track Roller    | OK          | OK    |  |
| Shoe Link       | OK          | OK    |  |

| Note for Upper Structure  |
|---|
| - The bottom of the bucket is worn  |
| - No bucket side cutters  |
|  |

| Note for Undercarriage  |
|---|
|  |

| Engine           |               |
|------------------|---------------|
| Model            | 3TNV76-P      |
| Serial Number    | 29033         |
| Engine Oil Leak  | No oil leak   |
| Engine Oil Gauge | OK            |
| Radiator         | Normal        |
| Exhaust Color    | Normal        |
| Blow-by          | No            |
| Engine Sound     | OK            |
| Hydraulic Pump   | No oil leak   |
| Water Pump       | No water leak |
| Oil Cooler       | No oil leak   |
| Motor            | Unchecked     |
| Multi Lever      | No oil leak   |

| Note for Operating Component  |
|---|
| The seat is partly damaged  |
|  |

| Note for Engine   |
|---|
|  |

Admin No. 2018060933