



Inspection Report


Inspection Date: 2018/06/11

Excavators


General Information			
Maker	HITACHI		
Model Number	ZX55UR		
Year	2004		
Hour (h)	3577	Meter	Working
Serial Number	10716		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		490		


Note for External Appearance
VIN stamping is unchecked


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Slide arm


Note for Undercarriage
The shoes are partly loose


Engine	
Model	CC-4LE2
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2018061573