



Inspection Report

Inspection Date: 2025/06/24

Excavators

General Information

Maker	KUBOTA		
Model Number	U40-6		
Year			
Hour (h)	4322	Meter	Working
Serial Number	11355		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		550		

Note for External Appearance



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket side cutters
- The arm has been reinforced



Note for Undercarriage



Engine

Model	V2607
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

- Oil oozing from the control valve



Admin No. 3000074451

*This report is only for your reference. We are not responsible for the actual condition of checked item.