



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	AICHI
Model Number	SV04B
Year	2006
Hour (h)	
Serial Number	700008

Note for External Appearance

- The battery charging cable is missing
- The cell is missing

Engine

Model	
Serial Number	
Engine Oil Leak	#N/A
Engine Oil Gauge	#N/A
Exhaust Color	#N/A
Blow-by	#N/A
Engine Sound	#N/A
Radiator	#N/A
Water Pump	#N/A
Injection Pump	#N/A

Note for Control Panel

Note for Engine

- Battery type

Other Information

- Operation is unchecked
- Working hour is unknown

Admin. No. 3000045975

*This report is only for your reference. We are not responsible for the actual condition of checked item.