



Inspection Report

Inspection Date: 2018/12/06


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-30-5		
Year	2014		
Hour (h)	556	Meter	Working
Serial Number	79377		

Options	
- CNP	- Speed changer
- Blade	- Breaker Pipings
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	N/A	
Arm		No	No	Small
Bucket		No	No	Unchecked
Bucket Size (mm)		430		

Note for External Appearance




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
A standard bucket will be attached before shipment




Note for Undercarriage
Rusty




Engine	
Model	
Serial Number	7EZ0090
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018110343