



Inspection Report


Inspection Date: 2018/07/23

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC138US-2E1		
Year	2005		
Hour (h)	5510	Meter	Working
Serial Number	6257		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Unchecked
Bucket Size (mm)				


Note for External Appearance


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- A bolt of the stay of the right piping is lost - The attachment in the picture is NOT for sale and will be replaced with a standard bucket


Note for Undercarriage


Engine	
Model	SAA4D95LE-3-A
Serial Number	110278
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2018070743