



Inspection Report

Inspection Date: 2019/02/05

Wheel Loader

General Information

Maker	YANMAR
Model Number	V3-5
Year	1999
Hour (h)	1937
Serial Number	L3D-51038

Note for External Appearance

- According to the seller, operational condition has been checked and there is no problem
- The body is rusty



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure

Upper structure movement is unchecked



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component



Engine

Model	3TNE84-EKAH
Serial Number	45294
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

- Tire size: 125/70-16 6 P.R.
- Traveling and steering motion are unchecked



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine

Operational condition of the engine is unchecked because there is no battery



Admin. No. 2019010237

*This report is only for your reference. We are not responsible for the actual condition of checked item.