



Inspection Report

Inspection Date: 2019/02/21

Excavators

General Information

Maker	KUBOTA		
Model Number	U-15-3S		
Year			
Hour (h)	2641	Meter	Working
Serial Number	42292		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	400			

Note for External Appearance



Note for Upper Structure

The bottom of the bucket is worn and has some holes



Undercarriage

Shoe Type	Rubber		
Swing Circle	Unchecked		
		Left	Right
Shoe Width (mm)	235	235	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Undercarriage



Engine

Model	D782-K2A
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	Unchecked
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2019020526