



Inspection Report

Inspection Date: 2024/08/02

Excavators

General Information

Maker	YANMAR		
Model Number	B6-6A		
Year	2013		
Hour (h)	3943	Meter	Working
Serial Number	66354		

Options


- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	400			

Note for External Appearance

- The covers have some rust and scratches




Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- Oil oozing from the bottom cover
- Oil oozing from the hose near the hydraulic pump



Note for Undercarriage

- The rubber shoes are cracked




Engine

Model	4TNV88-BXBVD
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- The crane monitor is unable to read due to film deterioration



Note for Engine

- Slight blow-by



Admin No. 3000061593