



Inspection Report

Inspection Date: 2018/08/08

Truck

General Information

| | |
|----------------------|---------------|
| Maker | mitsubishi |
| Model Number | KK-FE71CBD |
| Year | 2004 |
| Mileage (km) | 155298 |
| Serial Number | FE71CB-505603 |

Engine

| | |
|-------------------------|---------------|
| Model | 4D33 |
| Serial Number | 5AZF8601 |
| Engine Oil Leak | No |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Radiator | OK |
| Water Pump | No water leak |
| Injection Pump | No fuel leak |

Note for External Appearance

- High bed
- Trailer: KYOKUTO DD02-31
- Load capacity: 2,000kg
- Studless tires
- Tire size: 195/85R16 114/112L LT

Note for Control Panel

- 5-speed column shift
- SRS airbag
- The vehicle inspection will expire on Jan. 31, 2019

Note for Engine

Motor: 4D33, 4,210L

Admin. No. 2018070649

*This report is only for your reference. We are not responsible for the actual condition of checked item.