

Inspection Report

Inspection Date: 2018/04/12

Generator

General Information	
Maker	DENYO
Model Number	DCA-60ESH
Year	2002
Hour (h)	
Serial Number	3710898

Engine

WO4D-TG
No oil leak
ОК
Normal
No
ОК
ОК
No water leak
No fuel leak

Note for External Appearance

The rear cover has some dents

Note for Control Panel

The hour meter has been replaced (unable to check the correct meter)

Note for Engine

2018040356

Admin. No.

*This report is only for your reference. We are not responsible for the actual condition of checked item.