



Inspection Report

Inspection Date: 2024/08/23

Excavators

General Information

Maker	KOBELCO		
Model Number	SK125SR		
Year	2014		
Hour (h)	7413	Meter	Working
Serial Number	YV06-07613		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	- PIPINGS

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	805			

Note for External Appearance

- The body is deteriorated and rusted over time
 - The right rear cover has some dents




Undercarriage

Shoe Type	Steel		
Swing Circle	Oil oozing		
		Left	Right
Shoe Width (mm)	700	700	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The bucket side cutters are missing



Engine

Model	D04FR
Serial Number	19195
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000062807