



Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-2E1		
Year	2006		
Hour (h)	7118	Meter	Working
Serial Number	KMTPC043C01007679		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	Oil leak	No	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		850		

Note for External Appearance

- The covers have some dents



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage



Engine

Model	SAA4D95LE-3
Serial Number	
Engine Oil Leak	Oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	Oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine

- Oil oozing from the control valve



Admin No. 3000051045

*This report is only for your reference. We are not responsible for the actual condition of checked item.