



Inspection Report


Inspection Date: 2017/10/13

Excavators


| General Information | | | |
|---------------------|---------|-------|---------|
| Maker | YANMAR | | |
| Model Number | ViO20-3 | | |
| Year | 2004 | | |
| Hour (h) | 3371 | Meter | Working |
| Serial Number | 31051B | | |


| Options | |
|--------------|-------------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Breaker Pipings |
| - EPA | |

| Upper Structure | | | | |
|------------------|-------|------------|--------------|------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Big |
| | Right | N/A | N/A | |
| Arm | | No | No | Big |
| Bucket | | Oil oozing | No | Big |
| Bucket Size (mm) | | 420 | | |


| Note for External Appearance |
|---|
| Repainted |
|  |


| Undercarriage | | |
|-----------------|-------------|-------|
| Shoe Type | Rubber | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 250 | 250 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

| Note for Upper Structure |
|---|
|  |

| Note for Undercarriage |
|---|
|  |

| Engine | |
|------------------|---------------|
| Model | 3TNV76-P |
| Serial Number | 6344 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
|  |

| Note for Engine |
|---|
| The battery does not have enough power |
|  |

Admin No. 2017100746