



Inspection Report

Inspection Date: 2026/04/28

Excavators

General Information

Maker	KOMATSU		
Model Number	PC30UUC-6		
Year	2022		
Hour (h)	2815	Meter	Working
Serial Number	KMTPC266VNE005385		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	410			

Note for External Appearance

- The whole body has scratches and rust
- The covers have some dents



Undercarriage

Shoe Type	Rubber		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- No bucket side cutters



Note for Undercarriage

- The rubber shoes are deteriorated



Engine

Model	3D88E-6ESCA
Serial Number	47621
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

- The battery is flat



Admin No. 3000083773