



Inspection Report

Inspection Date: 2022/11/21

Dozer

General Information

Maker	KOMATSU
Model Number	D21A-7E-A
Year	2001
Hour (h)	3680
Serial Number	D207B-81760

Note for External Appearance



Upper Structure

Blade Tilt Cylinder	No oil leak	
	Left	Right
Lift Arm Cylinder	No oil leak	No oil leak
Blade Angle Cylinder	No oil leak	No oil leak
Travel Motor	No oil leak	No oil leak

Note for Upper Structure



Note for Operating Component

- The seat has been repaired
- Canopy type



Undercarriage

	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Shoe Link	OK	OK
Sprocket	OK	OK
Track Roller	OK	OK
Upper Roller	OK	OK
Pin Bush	OK	OK

Note for Undercarriage



Engine

Model	4D94E-1AH
Serial Number	03570
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Engine

- EPA



Admin. No. 3000044379

*This report is only for your reference. We are not responsible for the actual condition of checked item.