

Inspection Date: 2019/02/19


| General Information | | |
|----------------------------|------------|---------|
| Maker | YANMAR | |
| Model Number | Vio40-5 | |
| Year | 2007 | |
| Hour (h) | 4794 Meter | Working |
| Serial Number | 51619B | |

| Options | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |
| - EPA | |

| Upper Structure | | | | | |
|----------------------|----------|----------|--------------|-------|--|
| | | Cylinder | | Play | |
| | | Oil Leak | Scratch/Rust | . lay | |
| Boom | Left | No | No | Small | |
| | Right | N/A | N/A | Oman | |
| | Arm | No | No | No | |
| Bucket | | No | No | Small | |
| Bucket S | ize (mm) |) 560 | | | |
| Bucket Size (mm) 560 | | | | | |

| Note for External Appearance | |
|------------------------------|--|
| | |
| | |
| | |
| | |
| | |

| Undercarriage | | |
|-----------------|------------------------------|-------|
| Shoe Type | Steel shoes with rubber pads | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 350 | 350 |
| ldler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |







| Note for Engine | |
|--|------------|
| - The battery is flat - The engine works properly with booster cables - Unable to check the engine room thoroughly | |
| Admin No. | 2019020349 |