



# Inspection Report

Inspection Date: 2025/10/30

## Excavators

### General Information

Maker	KUBOTA		
Model Number	RX-306E		
Year	2018		
Hour (h)	2053	Meter	Working
Serial Number	23888		

### Options

- CAB	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		430		

### Note for External Appearance

- Repainted
- The body has scratches and rust
- The muffler is corroded



### Note for Upper Structure



### Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage



### Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000077513

\*This report is only for your reference. We are not responsible for the actual condition of checked item.