



Inspection Report

Inspection Date: 2023/12/17

Excavators

General Information

Maker	KOMATSU		
Model Number	PC128US-8		
Year	2011		
Hour (h)	7440	Meter	Working
Serial Number	KMTPC189A01028068		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	Oil oozing	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	830			

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	NG	
Shoe Link	OK	OK	

Note for Upper Structure

-The arm was reinforced (outside & inside)



Note for Undercarriage

- Oil oozing from one of the 1 right lower roles



Engine

Model	SAA4D95LE-5-A
Serial Number	528861
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

-The seat is torn



Note for Engine



Admin No. 3000053595