



# Inspection Report

Inspection Date: 2018/06/15


## Excavators

General Information			
Maker	YANMAR		
Model Number	B6-6		
Year	2006		
Hour (h)	4509	Meter	Working
Serial Number	60877B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		600		

Note for External Appearance
<ul style="list-style-type: none"> <li>- The body is partly painted</li> <li>- The light under the canopy is broken</li> <li>- The handle of the engine cover is lost</li> </ul>




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure




Note for Undercarriage
The rubber shoes have deteriorated over time, are worn, and partly cracked



Engine	
Model	4TNV88-P
Serial Number	39205
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The canopy is partly deformed



Note for Engine



Admin No. 2018061069